

The TRIUMPH Corporation

SERVICE BULLETIN

Bulletins 62/10, 63/8 and 65/2 Revised October 7, 1965

65/12

RE: Lucas Stators and Rotors Fitted to Triumph Motorcycles - 1954 thru 1966.

"A" RANGE

RM No.	STATOR PART No.	NUMBER OF LEADS-COILS	ROTOR PART No.	No. STAMPED ON ROTOR	MODEL	YEAR
RML 3	465915 Use 468678*	3 - 6	466124	465904	T15, T20 & T20C	54-55
RML 3	47119 is 468678	3 - 6	"	"	T20	56-61
RML 3	47138 ***	3 - 4	"	"	T20S E.T.Ign.	59
RML 3	47175 ***	3 - 6	"	"	T20S & T20W E.T.Ign.	60
RML 3	47177	4 - 6	"	"	T20S, T20SL & T20T E.T.Ign.	61
RML 3	47168 Use 468678	3 - 6	"	"	T20	62
RML 8	47161	3 - 6	54213903	54212284	T20	62-65
RML 3	47166 ***	4 - 6	466124	465904	T20SR & T20SC E.T.Ign.	62
RML 9	47173	4 - 6	54213901	54212006	T20SR, T20SC & T20SM E.T.Ign.	63-66

"B" RANGE

RML 4	466168	3 - 6	466230	465969	5T & 6T	54-58
RML 5	47127 is 469427	3 - 6	423506	466177	6T	59-61
RML 3/15	High Medium Low Out-put					
	47134-47178 -47171	3 - 6	423506	466177	T110, T120, TR7 & TR6	60-61
RML 9	47183 Low Out-put	3 - 6	54213901	54212006	T120R, TR6SR & TR6SC	62
RML 9	47164 **	3 - 6	54213901	54212006	6T	62
RML 9	47162	3 - 6	54213901	54212006	6T, TR6 & T120	63-66-7
RML 9	47188	5 - 6	54213901	54212006	T120/TT SPEC. (E.T.Ign.)	63-66
				(or) 54215824		

"C" RANGE

RML 3/15	47124 is 468973	3 - 6	423506	466177	3TA & 5TA	58-61
RML 9	47162	3 - 6	54213901	54212006	3TA, 5TA & T100SR	62-66
RML 9	47173	4 - 6	54214272	Use 54213901	- T100SC E.T.Ign.	62
RML 3/15	47149	5 - 6	54211596	54211595	1960 T100A & TR5AR E.T.Ign.	61
					up to Engine # H21122	
RML 3/15	47124 is 468973	3 - 6	54211596	54211595	TR5AR Battery-Coil Ign.	61
					after Engine #H 21122	
RML 3/15	47177	4 - 6	54211596	54211595	TR5AC E.T.Ign. up to	61
					Engine #H 25251	
RML 9	47188	5 - 6	54213901	54212006	T100SC E.T.Ign.	63-66
				(or) 54215824		

* Can use 47178 in place of 468678

** 47181 Supersedes 47164

*** Use 47177