

The TRIUMPH Corporation

SERVICE BULLETIN

March 20, 1967

TO ALL EASTERN TRIUMPH DEALERS:

Re: Index of Service Bulletins

All yellow Service Bulletins are identified by a reference number indicating the year and the number of the bulletin in numerical sequence. (Example, bulletin - reference No. 65/6 is #6 bulletin issued in 1965). File these yellow bulletins in numerical sequence by reference number and date.

This is a revised index as of March, 1967. We have removed some of the obsolete bulletins from this index.

IMPORTANT NOTE: Whenever you receive a Service Bulletin always file it in numerical sequence and add the number and subject of the bulletin in the blank space provided on this index sheet.

<u>Bulletin</u> <u>Ref. No.</u>	<u>Date</u>	<u>Subject of Bulletin</u>
59/7	May 1, 1959	Refacing Clutch Plates, Twins and Lightweights
59/15	Aug. 20, 1959	Service Notes - 1959 Gearbox Fitted to Big Twin Models
<u>SERVICE BULLETINS FOR 1960</u>		
60/4	March 14, 1960	Ex Pipes & Mufflers Fitted to 1958, '59, & '60 "B" Range.
60/10	Sept. 27, 1960	CD223 Twin Carburetor Balance Tube Kit
<u>SERVICE BULLETINS FOR 1962</u>		
62/3	Jan. 13, 1962	Part #CD108 Spindle Puller - Instructions for Use on All Triumph S/A Models
62/4	May 25, 1962	Transmission Gears Available for Triumph Models '50-'62
62/6	Aug. 17, 1962	650cc Twin Crankshaft Assembly
62/7	Aug. 27, 1962	Lucas Switch Kit CD299
62/8	Aug. 31, 1962	Kit of Racing Valve Springs for Tiger Cub Models
62/11	Dec. 17, 1962	Universal Condenser, Part No. CD303
62/12	Dec. 19, 1962	1963 "A" Range Wiring Chart
62/13	Dec. 20, 1962	1963 "B" Range Wiring Chart

Continued.....

62/14 Dec. 19, 1962 1963 "C" Range Wiring
62/15 Dec. 20, 1962 Service Notes on the 1963 "C" Range T100S/R 500cc Twin

SERVICE BULLETINS FOR 1963

63/1 Jan. 7, 1963 Instructions for Testing Lucas RMI9 Equipment as Fitted to Both "B" & "C" Range '63 Battery Ignition Twin Models
63/2 Jan. 7, 1963 Instructions for Testing Lucas RMI8 Equipment as Fitted to 1962 & 1963 Battery Ignition T20 Cub Models
63/4 Jan. 23, 1963 Instructions for Fitting CD172/CS63 Mounting Brackets to 1963-T100S/R Saddlebag Brackets for 1963 "C" Range
63/5 Jan. 23, 1963 Instructions for Fitting CD172/B63 Saddlebag Mounting Bkts. to '63-T120/R & TR6/R Saddlebag Brackets for '63 "B" Range

The following Service Bulletins for 1964, '65, '66 and '67 and also ALL "Blue" Bulletins beginning with No. 4 (November 1963) are included in a special "Black Binder" that was sent to all Dealers during June 1966. This "Black Binder" set of Service Bulletins is for the use of Triumph Mechanics.

SERVICE BULLETINS FOR 1964

64/1 Jan. 17, 1964 Basic Instructions for Set-Up of NEW 1964 Triumph Twin Cylinder Motorcycles
64/2 Feb. 4, 1964 NEW SHOP TOOLS
64/4 Oct. 30, 1964 Wheel Building Dimensions

SERVICE BULLETINS FOR 1965

65/3 Jan. 18, 1965 1964 Type Fork Springs Fitted to "B" & "C" Range Twins
65/4 Feb. 22, 1965 Instructions for Mounting VDO Enduro Speedo
65/5 May 4, 1965 Use of Triumph Electrical Test Set Model 102
65/6 May 11, 1965 CD415 Luggage Rack - CD417 Saddlebag Brackets
65/7 July 7, 1965 376/077T Float Bowl Window Gauge
65/8 July 15, 1965 New "Red" Ignition Timer Disc CD376
65/9 July 23, 1965 Important Service Notes to be read by Sales and Service Personnel
65/10 Aug. 3, 1965 Rear Wheel Bearing Seal
65/11 Aug. 18, 1965 Alternative WISCO G-3A Battery
65/13 Oct. 8, 1965 Exchange Prices on Lucas Electrical Equipment

Continued.....

65/14	Oct. 12, 1965	Model 102 Electrical Test Set (D.C. Generator Models)
65/15	Oct. 12, 1965	Model 102 Electrical Test Set (T20 Model-RM18)
65/17	Nov. 9 , 1965	12 Volt Lucas Equipment Testing (1966 Models)
65/18	Dec.10, 1965	Countershaft Sprockets
65/19	Dec. 8, 1965	Rear Wheel Sprockets
65/20	Dec. 8, 1965	Chain Oiler-Late '65 Twin Models - Early '66 Models

SERVICE BULLETINS FOR 1966

66/1	Jan. 24, 1966	Oil Bleed Holes in Connecting Rods
66/2	Feb. 25, 1966	Tachometer Drive Gearbox
66/3	May 16, 1966	Jomo Valve Springs
66/4	July 1, 1966	Electrical Problems-Ignition Switch #31899 and Diode #49345
66/5	Aug. 5, 1966	Head Light Bulb Failures
66/6	Dec.14, 1966	Mounting CD472 Seat Rail for '67 "B" & "C" Range Models

SERVICE BULLETINS FOR 1967

67/1	Jan. 1, 1967	"Flat Rate" Labor Time Schedule
------	--------------	---------------------------------

The TRIUMPH Corporation

SERVICE BULLETIN

November 11, 1966

MECHANIC'S SERVICE BULLETINS 1964 - 1967 INDEX - REFERENCE BY SUBJECT

<u>SUBJECT</u>	<u>SERVICE BULLETIN REFERENCE NUMBERS</u>	
	<u>Yellow</u>	<u>Blue</u>
Camshafts - Racing		6
Carburetion		
Dual twist grip	65/9	
Float level	65/7	9
Float needle and seat		10
Throttle slides - sticking		6
Throttle slides - 1966 T120/R		14
Chain Oiler	65/9 & 65/20	11
Connecting rods - oil holes	66/1	
Electrics - Replacement Parts		
Battery - new 6 volt	65/11	
Battery - new 12 volt		13, 14 & 17
Contact breaker plate		10
Cut-out button - Ignition		13
Key - Ignition		11
Stators & rotors - Part Nos. & Exch. Prices	65/12 & 65/13	
Electrics - Service Problems and Testing		
Bulbs	66/5	16 & 19
Diode	66/4	11 & 16
Fuse		11
Heat sink		16
Ignition timing	65/8 & 65/9	6, 8 & 10
Switch - Ignition	66/4	
Switch - Lighting		8
Tail - Light		14
Electrics - Test Procedure		
1966 12 volt models	65/17	
1963 - '65 6 volt models	65/5	
1962 - '65 T20 Cub Battery Ignition Models	65/14	
Pre-1960 D.C. Generator Models	65/14	
Wiring color code 1963 - '64 models		5
Engine Number List of New '66 Improvements		15
Engine - Service Problem - Wet Sumping		17
Emblems - Gas Tank		11

Continued.....

November 11, 1966

	<u>Yellow</u>	<u>Blue</u>
Exhaust Pipes		
Loose exhaust adaptors		11, 13 & 17
Wrench for exh. adaptors & exh. pipe "Sizing" tool		11 & 13
Tool for exh. adaptors & repairing cylinder head		18
Forks - Service Notes 1964-'66 Type (outside springs)		4 & 6
Oil leaks		6, 8 & 11
Fork Springs	65/3	
Gearbox - Service Problem		19
Ignition - Problems - Timing	65/8 & 65/9	6, 8 & 10
Labor - Flat Rate Schedule	65/1	
Luggage Rack	65/6	
Oil Leaks	65/3	11
Forks		8 & 11
Loose oil lines		4, 19, 11 & 14
Primary case	65/9 & 65/20	
Push Rod Cover Tubes		11
Tachometer drive		14
Engine "Wet Sumping"		17
Replacement Parts Book / Corrections & Notes		
1964 #2 Parts Book "B" Range		7
1966 #4 Parts Book "B" Range		12
	65/6	
Saddlebag Brackets	65/6	
Speedometers		
Smith's Broken Glass Replacement		8
VDO Enduro Type	65/4	11
Sprockets - Part Number Listing	65/18 & 65/19	
Loose R/W sprocket bolts		14
Tachometers		14
Tank Emblems		11
Tappets - Exhaust Lubrication		13
Tires		13
Tools	65/4, 65/7 & 65/8	13 & 18
Valve Springs	66/3	
Vibration		11
Wet-Sumping		17
Wheel Bearing	65/10	