BSA SERVICE SHEET No. 402

Reprinted October, 1958.




Fig. C2. The CII Engine (Exploded View)

1854 SERVICE SHEET No. 402A

