

The TRIUMPH Corporation

Parts - Tools - Accessories Bulletin

February 3, 1967

Bulletin 67-4P

(Supersedes Service Bulletins 62/10, 63/8, 65/2 and 65/12)

RE: Lucas Stators and Rotors Fitted to Triumph Motorcycles - 1954 thru 1967.

"A" RANGE

RM No.	STATOR PART No.	NUMBER OF LEADS-COILS	ROTOR PART No.	No. STAMPED ON ROTOR	MODEL	YEAR
RM13	47105	3 - 6	466124	465904	T15, T20 & T20C	54-62
RM13	47177	4 - 6	466124	465904	T20S, T20W, T20SL, T20T, T20SR, & T20SC E.T. Ign.	59-62
RM18	47161	3 - 6	54213903	54212284**	T20 (w/two piece crankcase)	62-65
RM19	47188*	5 - 6	54213901	54215824**	T20SR, T20SC, T20SM E.T. Ign. (w/two piece crankcase)	62-67

"B" RANGE

RM14	466168	3 - 6	466230	465969	5T & 6T	54-58
RM15	47127	3 - 6	423506	466177	6T	59-61
RM13/15	47171	3 - 6	423506	466177	T110, T120, TR7 & TR6	60-61
RM19	47183	3 - 6	54213901	54215824**	T120R, TR6SR, & TR6SC	62
RM19	47181	3 - 6	54213901	54215824**	6T	62
RM19	47162	3 - 6	54213901	54215824**	6T, TR6 & T120	63-67
RM19	47188	5 - 6	54213901	54215824**	T120TT & TR6C	63-67

"C" RANGE

RM13/15	47105	3 - 6	423506	466177	3TA & 5TA	58-61
RM13/15	47149	5 - 6	54211596	54211595	1960 T100A & TR5AR E.T. Ign	61
RM13/15	47105	3 - 6	54211596	54211595	up to Engine #H21122 TR5AR Battery-Coil Ign	61
RM13/15	47177	4 - 6	54211596	54211595	after Engine #H21122 TR5AC E.T. Ign up to	61
RM19	47188*	5 - 6	54213901	54215824**	Engine #H25251	
RM19	47162	3 - 6	54213901	54215824**	T100SC E.T. Ign	62
RM19	47188	5 - 6	54213901	54215824**	3TA, 5TA & T100SR	62-67
					T100SC E.T. Ign	63-67

*The 47188 five lead Stator has superseded the 47173 four lead Stator previously fitted to E.T. Ignition models. In this application the black-yellow lead from the 47188 Stator must be grounded.

**54213901 rotor may be stamped either 54212006 or 54215824.

SUPERSESSIONS

47105---supersedes---47119, 47124, 47137, 47168, 465915, 468678, & 468973
 47127---supersedes---469427
 47171---supersedes---47134 & 47178
 47177---supersedes---47138, 47165, 47166, & 47175
 47181---supersedes---47164
 47188---supersedes---47173
 54213901---supersedes---54214272 & 54215824